

R32 Pressure-Temperature Chart

Saturation Pressure-Temperature Data for R32 (psig)*

Temp (°F)	Pressure Vapor (psig)	Temp (°C)
-40	11.0	-40.0
-35	14.4	-37.2
-30	18.2	-34.4
-25	22.3	-31.7
-20	26.8	-28.9
-15	31.7	-26.1
-10	37.1	-23.3
-5	42.9	-20.6
0	49.3	-17.8
5	56.1	-15.0
10	63.5	-12.2
15	71.5	-9.4
20	80.0	-6.7
25	89.2	-3.9
30	99.1	-1.1
35	109.7	1.7
40	121.0	4.4
45	133.0	7.2
50	145.9	10.0
55	159.5	12.8
60	174.1	15.6
65	189.5	18.3
70	205.8	21.1
75	223.2	23.9
80	241.5	26.7
85	260.9	29.4
90	281.3	32.2
95	302.9	35.0
100	325.7	37.8
105	349.6	40.6
110	374.9	43.3
115	401.4	46.1
120	429.3	48.9
125	458.6	51.7
130	489.4	54.4
135	521.8	57.2
140	555.7	60.0
145	591.4	62.8
150	628.8	65.6